



7 UNIT MOORING CLEAT DETAIL
SCALE 1 : 10 MTS.




RC CURB DETAIL
SCALE 1 : 100 MTS.




STAIR LANDING DETAILS
SCALE 1 : 100 MTS.


PHILIPPINE PORTS AUTHORITY	PROJECT TITLE: REPAIR OF DAMAGED PORT FACILITIES, AND BACK-UP AREA CAUSED BY TYPHOON ODETTE	PREPARED BY: VIOLETA D. ROBIN ENGINEERING ASSISTANT A	CHECKED/REVIEWED BY: BENJAM L. ALAUD SUPERVISING ENGINEER	RECOMMENDING APPROVAL: LORD TYRONE C. AGATON ACTING ESD MANAGER	APPROVED: BERNARD C. CALLEDO PORT MANAGER	SHEET CONTENTS: 14 / 32
-----------------------------------	--	--	--	--	--	-----------------------------------




TYPICAL SECTION OF TETRAPOD
SCALE 1 : 100 MTS



TETRAPOD WAVE BREAKER DETAIL



TETRAPOD WAVE BREAKER PLAN



TETRAPOD WAVE STEEL
REINFORCEMENT DETAIL


INSTALLATION OF TETRAPOD






PHILIPPINE PORTS AUTHORITY	PROJECT TITLE: REPAIR OF DAMAGED PORT FACILITIES AND BACK-UP AREA CAUSED BY TYPHOON ODETTE	PREPARED BY: VIOLETA R. ROBIN ENGINEERING ASSISTANT A	CHECKED/REVIEWED BY: REYGAN L. ALIAD SUPERVISING ENGINEER	RECOMMENDING APPROVAL: LORD TYRON L. AGATON ACTING ESD MANAGER	APPROVED: BERNARD C. CALLEDO PORT MANAGER	SHEET CONTENTS: 15 / 32
-----------------------------------	--	--	--	---	--	-----------------------------------





322 215 322 117

YOU ARE NOW LEAVING PORT OF LIMASAWA





 PHILIPPINE PORTS AUTHORITY		PROJECT TITLE:		PREPARED BY:		CHECKED/REVIEWED BY:		RECOMMENDING APPROVAL:		APPROVED:		SHEET CONTENTS:		
REPAIR OF DAMAGED PORT FACILITIES AND BACK-UP AREA CAUSED BY TYPHOON ODETTE		LOCATION: PORT OF LIMASAWA, LIMASAWA ISLAND		 <u>VIOLETA D. ROBIN</u> ENGINEERING ASSISTANT A		 <u>REYGAN L. ALALID</u> SUPERVISING ENGINEER		 <u>LORD THYRONNE A. AGATON</u> ACTING ESD MANAGER		 <u>BERNARD C. CALLEDO</u> PORT MANAGER				18/ 32











ACCESS BOOM BARRIER

	PROJECT TITLE: REPAIR OF DAMAGED PORT FACILITIES AND BACK-UP AREA CAUSED BY TYPHOON ODETTE LOCATION: PORT OF LIMASAWA, LIMASAWA ISLAND	PREPARED BY: VIOLETA ROBIN ENGINEERING ASSISTANT A	CHECKED REVIEW BY: REYGAN L. ALID SUPERVISING ENGINEER	RECOMMENDING APPROVAL: LORD TYRNONE L. AGATON ACTING ESD MANAGER	APPROVED: BERNARD C. CALLEDO PORT MANAGER	SHEET CONTENTS:	23 / 32
--	--	---	---	---	--	-----------------	---------

