

PMO PALAWAN BIDS AND AWARDS COMMITTEE

SUPPLEMENTAL / BID BULLETIN 6

NRP-PLW-01-2021 REPAIR OF DAMAGED R.C. WHARF, RORO RAMP NO. 2 AND BACK-UP AREA, PORT OF PUERTO PRINCESA, PALAWAN

This Supplemental/Bid Bulletin No. 2 is issued to modify and amend provisions in the Bidding Documents.

AMENDMENT TO THE BILL OF QUANTITIES							
FROM				ТО			
NO	DESCRIPTION OF WORK	UNIT	QTY	NO	DESCRIPTION OF WORK	UNIT	QTY
(1)	(2)	(3)	(4)	(1)	(2)	(3)	(4)
BILL NO.	REPAIR OF RORO RAMP			BILL NO.	REPAIR OF RORO RAMP		
3.01	Disposal of Damaged R.C. Slab	cu.m.	59.40	3.01	Disposal of Damaged R.C. Slab	cu.m.	59.40
3.02	Disposal of Concrete Debris	cu.m.	59.40	3.02	Disposal of Concrete Debris	cu.m.	59.40
3.03	Supply and Install Reinforcing Bars for Item 3.04	kg.	13,362.51	3.03	Supply and Install Reinforcing Bars for Item 3.04	kg.	13,362.51
3.04	Supply and Place 3,500 psi Concrete for R.C. Slab	cu.m.	59.40	3.04	Supply and Place 3,500 psi Concrete for R.C. Slab	cu.m.	59.40
3.05	Supply and Place 3,500 psi Concrete for R.C. Slab	unit	6.00	3.05	Re-orientation of RDF and Replacement of Missing/Damaged SS Bolts	unit	6.00

This Supplemental Bid Bulletin No. 2 shall form part of the Bidding Documents. Any provisions in the Bidding Documents inconsistent herewith is hereby amended, modified and superseded accordingly.

For the guidance and information of all concerned.

Issued this 17th day of September 2021 at Port of Puerto Princesa, Palawan.

Reviewed and approved by:

RASY M. DE GUZMAN

Member

(sgd) MARITES C. COHEN

Member

ALLAN'S. MANUEL

Member

(sgd)

ERWIN S. GATPANDAN Vice Chairperson

Chairperson